



CERTIFICATE OF SERVICE · KITCHEN EXHAUST SYSTEM · SPECIMEN

Serviced & certified to AS 1851-2012

SAM-CERT-0000-SPEC · Compliant with limitations – listed below · Site: [REDACTED] · Date: [REDACTED]

POSITION	BEFORE	AFTER	RESULT
AP-1 · canopy plenum	1,400 µm	40 µm	Within criteria
AP-2 · horizontal run	900 µm	30 µm	Within criteria
AP-3 · riser base	2,600 µm	50 µm	Within criteria
Riser above AP-3	–	–	Not accessed · register #1

Acceptance: after cleaning, no single test above 50 µm (AIRAH Best Practice Guide 2022, §5.10). Between services the system mean is kept below 200 µm (§5.8.2); localised deposits of 2,000 µm or more are cleaned urgently (§4.4). Criteria are the guide’s, never attributed to AS 1851-2012. Illustrative values, in µm.

#	LOCATION	SEVERITY	RECOMMENDED ACTION
1	Riser above AP-3	Major	Install access panel; service on next visit
2	Fan discharge cowl	Minor	Fit rooftop containment; monitor

This is a specimen. Every value is illustrative. An issued certificate carries the site and address, the date and window of service, the technician, the purchase order and site references, the identical-position photographs by reference, and one of two statuses: compliant, or compliant with limitations. What was not reached is written on it with the reason and the remedy.